



HQ/W-3/12	Re = 100000	Ma = 0.000	Ncrit = 9.000
HQ/W-3/12	Re = 200000	Ma = 0.000	Ncrit = 9.000
HQ/W-3/12	Re = 400000	Ma = 0.000	Ncrit = 9.000
HQ/W-3/12	Re = 800000	Ma = 0.000	Ncrit = 9.000
HQ/W-3/12	Re = 70000	Ma = 0.000	Ncrit = 9.000
HQ/W-3/12	Re = 50000	Ma = 0.000	Ncrit = 9.000
HQ/W-3/12	Re $\sqrt{CL}$ = 100000	Ma $\sqrt{CL}$ = 0.000	Ncrit = 9.000



XF01L V 6.96